




B66 10M 64QAM 1@0 CH 132022




B66 10M 64QAM 50@0 CH 132022




B66 10M 64QAM 1@49 CH 132622




B66 10M 64QAM 50@0 CH 132622




B66 5M 64QAM 1@0 CH 131997




B66 5M 64QAM 25@0 CH 131997




B66 5M 64QAM 1@24 CH 132647




B66 5M 64QAM 25@0 CH 132647




B66 3M 64QAM 1@0 CH 131987




B66 3M 64QAM 15@0 CH 131987




B66 3M 64QAM 1@14 CH 132657




B66 3M 64QAM 15@0 CH 132657



B66 1.4M 64QAM 1@0 CH 131979



B66 1.4M 64QAM 6@0 CH 131979



B66 1.4M 64QAM 1@5 CH 132665



B66 1.4M 64QAM 6@0 CH 132665



APPENDIX 1 PHOTOS OF TEST SETUP

See test photos attached in Appendix 1 for the actual connections between Product and support equipment.

APPENDIX 2 PHOTOS OF EUT CONSTRUCTIONAL DETAILS

Refer to Appendix 2 for EUT external and internal photos.

*** End of Report ***

The test report is effective only with both signature and specialized stamp. The result(s) shown in this report refer only to the sample(s) tested. Without written approval of UnionTrust, this report can't be reproduced except in full.
