




## Test Set Up Photographs Radiated

Photograph 1: Front View Radiated Emissions – Below 1000 MHz – Forward Pointed



Photograph 2: Back View Radiated Emissions 30 MHz to 1000 – Pointed Forwrd



## 313 West 12800 South, Suite 311, Draper, UT 84020 • (801) 260-4040




Photograph 3: View Conducted Emissions On Edge Placement




Photograph 4: View Conducted Emissions – Pointed Up



313 West 12800 South, Suite 311, Draper, UT 84020 • (801) 260-4040



Photograph 5: Front View Radiated Emissions – Above 1000 MHz



Photograph 6: Back View Radiated Emissions - Above 1000 MHz



313 West 12800 South, Suite 311, Draper, UT 84020 • (801) 260-4040



Photograph 7: Front View Conducted Emissions Worst-Case Configuration



Photograph 8: Back View Conducted Emissions Worst-Case Configuration



## **Reference Test Set Up Photographs**




Photograph 9: Reference Photo of Test Setup for Emissions Below 30 MHz



Photograph 10: Reference Photo of Test Setup for Emissions From 30 MHz to 1000 MHz





Photograph 11: Reference Photo of Test Setup for Emissions Above 1000 MHz