

INTERNAL PHOTOGRAPHS

This document contains 6 photographs


Photograph No.1
ES800SK2 smoke detector with cover removed



Photograph No.2
ES800SK2 smoke detector internal view




Photograph No.3
ES800SK2 smoke detector PCB front view



Photograph No.4
ES800SK2 smoke detector PCB second side view



Photograph No.5
RF PCB close view



Photograph No.6
RF PCB second side

