



Report No.: EED32Q80454001

## Page 20 of 22

## 7 Photographs

## 8.1 EUT Test Setup


















Report No. : EED32Q80453602 Page 42 of 44

## **8 PHOTOGRAPHS OF TEST SETUP**




AC Power Line Conducted Emission Test Setup



Radiated spurious emission Test Setup-1(Below 1GHz)



Report No.: EED32Q80453602 Page 43 of 44



Radiated spurious emission Test Setup-2(Above 1GHz)



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.









