



Report No. : EED32P80440601 Page 47 of 71

9 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1 With camera(Below 1GHz)



Radiated spurious emission Test Setup-2 With camera close up (Below 1GHz)



















Radiated spurious emission Test Setup-3 Without camera(Below 1GHz)



Radiated spurious emission Test Setup-4 Without camera close up (Below 1GHz)










Radiated spurious emission Test Setup-5 With camera (Above 1GHz)



Radiated spurious emission Test Setup-6 Without camera (Above 1GHz)














Page 50 of 71 Report No.: EED32P80440601



Radiated spurious emission Test Setup-7(Above 1GHz) There are absorbing materials under the ground.



Conducted Emissions Test Setup-1



















Report No.: EED32P80440601



