
SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.

Report No.: LCS1512282592E

## **TEST SETUP PHOTOGRAPHS**



1.1. Photo of Radiated Emissions Measurement (X Position)





Fig.2

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 1 of 2

## 1.2. Photo of Line Conducted Emissions Measurement

