

KES Co., Ltd.
3701, 40, Simin-daero 365beon-gil,
Dongan-gu, Anyang-si, Gyeonggi-do, 431-716, Korea
Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr

Test report No.: KES-SR-22T0016 Page (1) of (8)

APPENDIX E: DUT ANTENNA DIAGRAM & SAR TEST SETUP PHOTOGRAPHS



3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 431-716, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Test report No.: KES-SR-22T0016 Page (2) of (8)

DUT Antenna Diagram




Figure E-1 Antenna Location (Rear Side View)



3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 431-716, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Test report No.: KES-SR-22T0016 Page (3) of (8)

SAR Test Setup Photographs - Right Ear




Top Side from Flat Phantom (Separation Distance: 0 cm) - Right Ear



Bottom Side from Flat Phantom (Separation Distance: 0 cm) - Right Ear



3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 431-716, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Test report No.: KES-SR-22T0016 Page (4) of (8)



Right Ear & Front Side from Flat Phantom (Separation Distance: 0 cm) - Right Ear




Rear from Flat Phantom (Separation Distance: 0 cm) - Right Ear

This report shall not be reproduced except in full, without the written approval of KES Co., Ltd. The results shown in this test report refer only to the sample(s) tested unless otherwise stated.

The authenticity of the test report, contact shchoi@kes.co.kr



3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 431-716, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Test report No.: KES-SR-22T0016 Page (5) of (8)



Right Side from Flat Phantom (Separation Distance: 0 cm) - Right Ear



Left Side from Flat Phantom (Separation Distance: 0 cm) - Right Ear




3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 431-716, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Test report No.: KES-SR-22T0016 Page (6) of (8)

SAR Test Setup Photographs - Left Ear




Top Side from Flat Phantom (Separation Distance: 0 cm) - Left Ear



Bottom Side from Flat Phantom (Separation Distance: 0 cm) - Left Ear



3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 431-716, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Test report No.: KES-SR-22T0016 Page (7) of (8)



Left Ear & Front Side from Flat Phantom (Separation Distance: 0 cm) - Left Ear




Rear from Flat Phantom (Separation Distance: 0 cm) - Left Ear

This report shall not be reproduced except in full, without the written approval of KES Co., Ltd. The results shown in this test report refer only to the sample(s) tested unless otherwise stated.


The authenticity of the test report, contact shchoi@kes.co.kr



3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 431-716, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Test report No.: KES-SR-22T0016 Page (8) of (8)



Right Side from Flat Phantom (Separation Distance: 0 cm) - Left Ear



Left Side from Flat Phantom (Separation Distance: 0 cm) - Left Ear