


Test setup photographs for test reports 1032445



Photograph 1. Radiated spurious emissions test setup



Photograph 2. AC power line conducted emissions test setup